

MAS Task Detail Screen

Cost Center: XDATA 469 EC MAS No: 2 Title: PIPELINE INSPECTION

Task No	Freq	Description
001	M	LFM WILL MONTHLY INSPECT PIPELINE FROM SUSIUN CITY TO AREA F BULK STORAGE FACILITY. INSPECTION WILL BE PERFORMED BY WALKING THE ENTIRE PIPLINE CHECKING FOR LEAKS IN EACH PIT. THE INSPECTOR SHOULD CHECK FOR DIS-COLORATION OF SURROUNDING VEGETATION. ALSO CHECK TO ENSURE THE MARKERS(SIGNS) ARE LEGIBLE AND INFORMATION IS CURRENT.

Work Sequence Number: 1

Hours to perform Task: 27.000

Number of Occurances: 1

Total Task Hours: 27.000 (Hours X Occurances)

Crew Size: 3

Heavy Equip Required? N

EPS Standard Used? N

(1)Keys (2)List Hrs by Freq (4)Prev (5)Next (6)PMI Book (7)EPS Book  
(9)Modify (11)Add Task (12)Delete (15)Print (16)Return (32)Exit

R E C U R R I N G   W O R K   P R O G R A M

Inst Code/Shop: XDATA 469   EC   Description: PIPELINE INSPECTION  
 Equip Type/Num: 1763   0001   Location: SUISUN CITY TO AREA F  
 Work Order: XDATA 44317   Size or Cap: 12 MILES   Date Inst: 20010827  
 Fac Number: XDAT 01763   Trav/Wrk Zone: 00   00   MAS: 002  
 Rec Type/Stat: E   Num of Items: 001   Critical: Y

Start/Stop Mo: 00   00   Act Hrs:   Week   Sched   FY 2010:   72.5   FY 2007:   28  
 Cycle Month: 00   This   0.0   0.0   FY 2009:   112   FY 2006:   28  
 Schedule Day: 14   Last   0.0   26.5   FY 2008:   28   FY 2005:   36

Freq	Hvy	Crw	Wk	Est	Act	Nr of Times	Date	Act	Mod	Nxt	Sch				
I	S	Eqp	Siz	Day	Hrs	Hrs	Sc	Cp	Df	Sk	Perfmd	Sched	Sched	Act	Ind
M	S	N	3	THU	27.0	72.5	4	3			20091215	20100114	20100114		T

(ENT) Revw   (1) Keys   (9) Mod   (13) Help   (15) Print   (16) Rtrn  
 (18) Notes   (19) Dates   (21) Equip   (22) Materials   (28) Move   (32) EXI